



PRODUCT DATA SHEET

Floor cleaning - Industrial and deep cleaners

Wetrok Speedclean

Wetrok's quickest and most effective deep cleaner is classified as non-hazardous - it is also known as: troubleshooting industrial cleaner





Wetrok Speedclean



pH value (Concentrate): 8–9

Important ingredients:

Surfactants, Solvents, Chelating agents, Fragrances, Preservatives

Recommended dosage:



Stripping

3–5 l/10 l



Stripping

5 l/10 l

Removal of encrustations

5 l/10 l

METHODS
finder



APPLICATION

- High performance deep cleaner for linoleum and PVC
- Specially developed for deep cleaning using a scrubber-drier
- For removal of polymer and wax coatings
- For basic cleaning of washable and solvent-resistant floor coverings using a machine
- Excellent removal of even the most stubborn polymer coatings (crust remover)

PROPERTIES

- Non-hazardous
- Prevents the pads from sticking
- Low lather
- Contains solvents
- Slightly alkaline
- Scented

GOOD TO KNOW

- Rubber marks do not stand a chance against Speedclean

PLEASE NOTE

- Not suitable for floor coverings that are sensitive to solvents, e.g. coverings made of natural rubber or epoxy, asphalt and painted surfaces
- Use only for cleaning PU floor coverings without playing court lines
- Not suitable for acid-sensitive floor coverings

RECOMMENDED APPLICATION METHOD

Basic cleaning

Remove any loose dirt by means of dust-binding mopping/dry vacuuming. Apply the basic cleaning solution to the floor covering (at least 0.3 l/m²), allow it to take effect for 20 minutes without letting it dry out! Then scrub the floor with a scrubber-dryer and a suitable pad, without adding water. Then turn the water supply up to full, lower the suction nozzle, wet-scrub the floor and vacuum off the dissolved coating, dirt and the remaining cleaning product. Allow the covering to dry well.

Basic cleaning

Remove any loose dirt by means of dust-binding mopping/dry vacuuming. Apply the basic cleaning solution to the floor covering, allow it to take effect for 15 minutes without letting it dry out! Wet scrub with a single-brush machine and a suitable pad or brush. Vacuum off the dissolved coating, dirt and remaining cleaning product. Then rinse the floor thoroughly using clean water (up to approx. pH 7).

Scrub drying in a single work step

Pour the cleaning solution into the fresh water tank. Remove any loose dirt by means of dust-binding mopping/dry vacuuming. Scrub-dry the floor covering thoroughly with a scrubber-dryer and a suitable pad or brush.

STORAGE

Store in original container at 15 to 25°C and protected from sunlight. Keep container closed when not in use.

Durability (unopened): 24 Month

Wetrok AG shall have no liability whatsoever for damage caused by incorrect use. Observe special cleaning and care instructions from the floor covering manufacturer.