



PRODUCT DATA SHEET

Floor cleaning - Industrial and deep cleaners

Wetrok Indumat

Optimized for efficient industrial cleaning





Wetrok Indumat



pH value (Concentrate): 13–14

Important ingredients:

Surfactants, Solvents, Base, Chelating agents, Soap

Recommended dosage:



Maintenance cleaning

0.05 –0.1 l/10 l



Intermediate cleaning

0.2–0.5 l/10 l



Deep cleaning

1 l/10 l

**METHODS
finder**



APPLICATION

- High-performance deep and industrial cleaner
- For the removal of oil, grease and general industrial soiling
- For cleaning washable and solvent-resistant surfaces and floor coverings (PVC, natural and artificial stone, clinker, etc.)

PROPERTIES

- Low lather
- Highly alkaline
- Contains solvents
- Unscented

PLEASE NOTE

- Not suitable for maintenance cleaning of self-shine floor coverings
- Not suitable for linoleum, natural rubber, wooden flooring, asphalt, painted surfaces
- The scrubber-dryer including optionally available dosing system must be thoroughly cleaned after each use according to the operating instructions

RECOMMENDED APPLICATION METHOD

Scrub drying in a single work step

Pour the cleaning solution into the fresh water tank. Remove any loose dirt by means of dust-binding mopping/dry vacuuming. Scrub-dry the floor covering thoroughly with a scrubber-dryer and a suitable pad or brush.

Scrub drying in a two-step process

Pour the cleaning solution into the fresh water tank. Remove any loose dirt by means of dust-binding mopping/dry vacuuming. Scrub the floor covering thoroughly with a scrubber-dryer and a suitable pad or brush (without vacuuming). Leave the cleaning solution to take effect. Observe the contact time! Do not allow to dry out! Follow up with the scrubber-dryer (lower suction nozzle). Scrub-dry the floor covering.

Wet mopping, two-step process

Remove any loose dirt (e.g. dust-binding mopping/dry vacuuming). Soak the mop with cleaning solution, wring it out slightly, wet mop the floor covering. Allow the cleaning solution to take effect without letting it dry! Use the rinsed and thoroughly wrung-out mop to remove the dissolved dirt and the remaining cleaning solution.

STORAGE

Store in original container at 15 to 25°C and protected from sunlight. Keep container closed when not in use.

Durability (unopened): 24 Month

Wetrok AG shall have no liability whatsoever for damage caused by incorrect use. Observe special cleaning and care instructions from the floor covering manufacturer.